



說明	申報人：本所	施工日期：112 年 07 月 25 日
	地點：西平里農水路路燈 195485 附近 (座標：23.710541, 120.338821)	派工編號：1120724-2 道路修補)
施工照片		
施工結果照片		



說明	申報人：里長	施工日期：112 年 04 月 22 日
	地點：大同路 28 號	派工編號：1120420-2 道路修補)
施工照片		
施工結果照片		

說明	申報人：興新里長	施工日期：112 年 04 月 22 日
	地點：新興 12 之 10(左前)、 新興 8 之 20(左前)沿線	派工編號：1120420-1 道路修補)
施工照片		
	施工結果照片	
		





說明	申報人：里長	施工日期：112 年 05 月 23 日
	地點：馬公路 2-22 號巷內	派工編號：1120518-1 道路修補)
施工照片		
施工結果照片		




說明	申報人：大荖里長	施工日期：112 年 05 月 25 日
	地點：23.679, 120.366 23.679, 120.367、23.678, 120.368	派工編號：1120524-2 道路修補)
施工照片		
		
施工結果照片		

說明	申報人：本所	施工日期：112 年 06 月 02 日
	地點：往新庄農水路 (座標：23.712822, 120.368264)	派工編號：1120602-2 道路修補)
施工照片		
施工結果照片		

說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：土庫鎮興新里燈桿 203023 號前 (座標：23.659923, 120.366203)	派工編號：1120707-1 道路修補)
施工照片		
施工結果照片		



說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：土庫鎮石廟里農水路 (座標：23.694N, 120.394E)	派工編號：1120714-1 道路修補)
施工照片		
施工結果照片		

說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：土庫示範公墓	派工編號：1120717-3 道路修補)
施工照片		
施工結果照片		

說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：土庫鎮民族路 36 號前 (座標：23.706750, 120.361083)	派工編號：1120717-1 道路修補)
施工照片		
施工結果照片		

說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：新生街 7 巷 5 號斜對面 (座標：23.706039, 120.356615)	派工編號：1120711-1 道路修補)
施工照片		
施工結果照片		



說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：崙內里頂寮地區農水路	派工編號：1120717-2 道路修補)
施工照片		
施工結果照片		

說明	申報人：本所	施工日期：112 年 07 月 18 日
	地點：土庫鎮復興路 191 巷口 (座標：23.685444, 120.388287)	派工編號：1120715-1 道路修補)
施工照片		
施工結果照片		



說明	申報人：本所	施工日期：112 年 06 月 02 日
	地點：土庫鎮雲 99 鄉道 (座標：23.684749, 120.365022)	派工編號：1120602-3 道路修補)
施工照片		
		

說明	申報人：本所	施工日期：112 年 06 月 02 日
	地點：土庫鎮雲 101 鄉道 (座標：23.673233, 120.366804)	派工編號：1120602-1(道路修補)
施工照片	 <p>A worker is spreading a dark, granular material (likely asphalt or gravel) onto a road surface. A white sign is placed on the ground, reading: 土庫鎮公所 道路修補小組, 112.06.02, 道路修補工程, 土庫鎮雲101鄉道.</p>	 <p>A worker in a blue shirt and cap is using a hand roller to compact the material on a road surface.</p>
	 <p>A worker in a blue shirt and cap is using a hand roller to compact the material on a road surface.</p>	 <p>A worker is using a hand roller to compact the material on a road surface.</p>
施工結果照片	 <p>A worker in a blue shirt and cap is using a hand roller to compact the material on a road surface.</p>	 <p>A worker is using a hand roller to compact the material on a road surface.</p>

說明	申報人：崙內里長	施工日期：112 年 05 月 25 日
	地點：崙內 81-4 號前 (座標：23.687147, 120.352055)	派工編號：1120524-1 道路修補)
施工照片		
		
施工結果照片		

說明	申報人：南平里長	施工日期：112 年 05 月 23 日
	地點：馬光派出所前 (座標：23.705670, 120.356702)	派工編號：1120519-1 道路修補)
施工照片		
施工結果照片		

說明	申報人：石廟里長	施工日期：112 年 05 月 08 日
	地點：23.680495, 120.387077	派工編號：1120505-1 道路修補)
施工照片		
施工結果照片		

說明	申報人：里長	施工日期：112 年 04 月 22 日
	地點：埤腳中排	派工編號：1120420-1 道路修補)
施工照片		
施工結果照片		

說明	申報人：本所	施工日期：112 年 07 月 25 日
	地點：土庫鎮雲 99 鄉道 (座標：23.684547, 120.364987)	派工編號：1120724-1 道路修補)
施工照片		
施工結果照片		